



Cheap Carfax Autocheck Report - VIN Check 80% OFF Car History

Images of Damaged / salvage auction cars also available, contact us for details Go to carvin123.com

Detailed Report ~

2007 Honda Civic

Vehicle Identification Number: JHMFA36237S018913

➔ Search Another VIN (.../vehicle/land.php)



No Accident / Junk / Salvage / Insurance Records

No Accident / Junk / Salvage / Insurance Records



Vehicle Records Available: 98



Vehicle Age: 10 year(s)



Assembly Location: Suzuka, Mie, Japan



Body Style: Sedan



lg/2007/2007-honda/2007-honda-civic-lx-coupe+at/2007-honda-civic-lx-coupe-at-angular-rear.jpg)

(<https://d3rdv3saj7j6nd.cloudfront.net/images/vehicle/>

2007 Honda Civic
VIN: JHMFA36237S018913
Hybrid
1.3L Hybrid I4 110hp 123ft. lbs.

Detailed Vehicle History



Exleasingcar Car Auctions



30+ manufacturers, 200+ models,
5500+ cars.

Below are the historical events for this vehicle listed in chronological order. Any discrepancies will be in bold text.

Report Run Date: April 26, 2017 Vehicle: JHMFA36237S018913



98 VEHICLE HISTORY ISSUES FOUND

Date	:	Not offered
Mileage	:	
Source	:	Honda
Details	:	Roadside Assistance: Not offered
Date	:	2006
Mileage	:	
Source	:	Original Manufacturer
Details	:	Fuel Economy Test 40 MPG Hwy / 45 MPG City
Date	:	2006
Mileage	:	
Source	:	Original Manufacturer
Details	:	Shipped to Dealer - Original MSRP: 23195
Date	:	2006
Mileage	:	
Source	:	Original Manufacturer
Details	:	Manufactured in Suzuka, Mie, Japan
Date	:	09-05-2007
Mileage	:	
Source	:	NHTSA Recalls
Details	:	On Certain Sedan And Hybrid (cng) Vehicles, During Assembly, The Telescopic Steering Column Mechanism May Have Been Over-lubricated With Silicone Grease. Over Time, Some Of This Extra Grease May Drip On The Brake Light Switch Causing The Switch To Fail.
Date	:	09-05-2007
Mileage	:	
Source	:	NHTSA Recalls
Details	:	On Certain Vehicles, The Wheel Speed Sensor Housing Uses An O-ring Seal To Prevent Leakage To Or From The Wheel Bearing. If Assembled Improperly, The O-ring May Not Seal Properly Allowing Water To Enter The Wheel Bearing And Eventually Cause Damage To The Bearing, Especially In Areas Where Use Of Road Salt Is Prevalent. If The Driver Continues To Drive With This Condition It Is Possible For The Wheel Bearing To Become Loose, Which Could Cause The Bearing To Fail.
Date	:	11-01-2007
Mileage	:	
Source	:	NHTSA Recalls
Details	:	On Certain Compressed Natural Gas (cng) Vehicles, In The Event Of A Severe Interior Fire In The Area Of The Rear Seat, The Cng Tank May Be Heated Unevenly, Preventing The Pressure Relief Device From Venting The Contents Of The Tank As Designed.
Date	:	12-31-2007
Mileage	:	
Source	:	NMVTIS
Details	:	No Problems Reported
Date	:	12-31-2008
Mileage	:	

Source	:	NMVTIS
Details	:	No Problems Reported
Date	:	12-31-2009
Mileage	:	
Source	:	NMVTIS
Details	:	No Problems Reported
Date	:	2010
Mileage	:	36,000 mi.
Source	:	Honda
Details	:	BasicWarranty: Expired
Date	:	12-31-2010
Mileage	:	
Source	:	NMVTIS
Details	:	No Problems Reported
Date	:	03-02-2011
Mileage	:	
Source	:	NHTSA Recalls
Details	:	Honda Is Recalling Certain Model Year 2006-2007 Honda Civic Hybrid Vehicles. There Is A Potential For The Voltage Converter That Relays Power From The Integrated Motor Assist (ima) System To The Vehicle's Electrical Components To Fail.
Date	:	12-31-2011
Mileage	:	
Source	:	NMVTIS
Details	:	No Problems Reported
Date	:	2012
Mileage	:	60,000 mi.
Source	:	Honda
Details	:	PowertrainWarranty: Expired
Date	:	2012
Mileage	:	Unlimited mi.
Source	:	Honda
Details	:	CorrosionWarranty: Expired
Date	:	12-31-2012
Mileage	:	
Source	:	NMVTIS
Details	:	No Problems Reported
Date	:	12-31-2013
Mileage	:	
Source	:	NMVTIS
Details	:	No Problems Reported
Date	:	12-31-2014
Mileage	:	
Source	:	NMVTIS
Details	:	No Problems Reported

Date	:	12-31-2015
Mileage	:	
Source	:	NMVTIS
Details	:	No Problems Reported

Date	:	05-24-2016
Mileage	:	
Source	:	NHTSA Recalls
Details	:	Honda (american Honda Motor Co.) Is Recalling Certain Model Year 2009-2011 Acura Tsx, 2011 Tsx Wagon, 2010-2011 Acura Zdx, 2008-2011 Honda Accord, 2010-2011 Accord Crosstour, 2006-2011 Civic, Civic Hybrid, And Civic Gx, 2007-2011 Cr-v, 2010-2011 Fcx Clarity And Insight, And 2009-2011 Fit, And Pilot Vehicles Originally Sold, Or Ever Registered, In Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, The Northern Mariana Islands (saipan), And The U.s. Virgin Islands, Or "zone A." Additionally, Unless Already Included In "zone A" Above, Honda Is Recalling Certain Model Year 2008 Honda Accord, 2006-2008 Civic, Civic Hybrid And Civic Gx, And 2007-2008 Cr-v Vehicles Originally Sold, Or Ever Registered, In Arizona, Arkansas, Delaware, The District Of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, And West Virginia, Or "zone B." Vehicles Not Originally Sold Or Ever Registered In Either Zones A Or B Are Not Subject To This Safety Recall. These Vehicles Are Equipped With Certain Air Bag Inflators Assembled As Part Of The Passenger Frontal Air Bag Modules, And Used As Original Equipment Or Replacement Equipment. In The Event Of A Crash Necessitating Deployment Of The Front Air Bags, These Inflators May Rupture Due To Propellant Degradation Occurring After Long-term Exposure To Absolute Humidity And Temperature Cycling.

Date	:	05-24-2016
Mileage	:	
Source	:	NHTSA Recalls
Details	:	Honda (american Honda Motor Co.) Is Recalling Certain Model Year 2009-2011 Acura Tsx, 2011 Tsx Wagon, 2010-2011 Acura Zdx, 2008-2011 Honda Accord, 2010-2011 Accord Crosstour, 2006-2011 Civic, Civic Hybrid, And Civic Gx, 2007-2011 Cr-v, 2010-2011 Fcx Clarity And Insight, And 2009-2011 Fit, And Pilot Vehicles Originally Sold, Or Ever Registered, In Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, The Northern Mariana Islands (saipan), And The U.s. Virgin Islands, Or "zone A." Additionally, Unless Already Included In "zone A" Above, Honda Is Recalling Certain Model Year 2008 Honda Accord, 2006-2008 Civic, Civic Hybrid And Civic Gx, And 2007-2008 Cr-v Vehicles Originally Sold, Or Ever Registered, In Arizona, Arkansas, Delaware, The District Of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, And West Virginia, Or "zone B." Vehicles Not Originally Sold Or Ever Registered In Either Zones A Or B Are Not Subject To This Safety Recall. These Vehicles Are Equipped With Certain Air Bag Inflators Assembled As Part Of The Passenger Frontal Air Bag Modules, And Used As Original Equipment Or Replacement Equipment. In The Event Of A Crash Necessitating Deployment Of The Front Air Bags, These Inflators May Rupture Due To Propellant Degradation Occurring After Long-term Exposure To Absolute Humidity And Temperature Cycling.

Date	:	12-31-2016
Mileage	:	
Source	:	NMVTIS
Details	:	No Problems Reported

Date	:	01-10-2017
Mileage	:	
Source	:	NHTSA Recalls
Details	:	Honda (american Honda Motor Co.) Is Recalling Certain 2009-2012 Acura Tsx, 2011-2012 Acura Tsx Wagon, 2010-2012 Acura Zdx, 2008-2012 Honda Accord, 2010-2012 Honda Accord Crosstour And Honda Insight, 2009-2012 Honda Fit, 2009-2012 Pilot, 2007-2011 Honda Cr-v, 2012 Honda Fcx Clarity And 2006-2011 Honda Civic, Civic Hybrid, Civic Ngv Vehicles Originally Sold, Or Ever Registered, In Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, The Northern Mariana Islands (saipan), And The U.s. Virgin Islands, Or "zone A." Additionally, If Not Included In "zone A" Above, Honda Is Recalling Certain 2009 Acura Tsx, Honda Fit And Pilot, 2008-2009 Honda Accord, 2006-2009

Civic, Civic Hybrid And Civic Ngv, And 2007-2009 Honda Cr-v Vehicles Originally Sold, Or Ever Registered, In Arizona, Arkansas, Delaware, District Of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, And West Virginia, Or "zone B." Additionally, If Not Included In "zone B" Above, Honda Is Recalling Certain 2008 Honda Accord, 2006-2008 Honda Civic, Civic Hybrid And Civic Ngv And 2007-2008 Honda Cr-v Vehicles Originally Sold, Or Ever Registered, In Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, And Wyoming. These Vehicles Are Equipped With Certain Air Bag Inflators Assembled As Part Of The Passenger Frontal Air Bag Modules Used As Original Equipment Or Replacement Equipment. In The Event Of A Crash Necessitating Deployment Of The Front Air Bags, These Inflators May Rupture Due To Propellant Degradation Occurring After Long-term Exposure To Absolute Humidity And Temperature Cycling.

Date	:	01-10-2017
Mileage	:	
Source	:	NHTSA Recalls
Details	:	Honda (american Honda Motor Co.) Is Recalling Certain 2009-2012 Acura Tsx, 2011-2012 Acura Tsx Wagon, 2010-2012 Acura Zdx, 2008-2012 Honda Accord, 2010-2012 Honda Accord Crosstour And Honda Insight, 2009-2012 Honda Fit, 2009-2012 Pilot, 2007-2011 Honda Cr-v, 2012 Honda Fcx Clarity And 2006-2011 Honda Civic, Civic Hybrid, Civic Ngv Vehicles Originally Sold, Or Ever Registered, In Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, The Northern Mariana Islands (saipan), And The U.s. Virgin Islands, Or "zone A." Additionally, If Not Included In "zone A" Above, Honda Is Recalling Certain 2009 Acura Tsx, Honda Fit And Pilot, 2008-2009 Honda Accord, 2006-2009 Civic, Civic Hybrid And Civic Ngv, And 2007-2009 Honda Cr-v Vehicles Originally Sold, Or Ever Registered, In Arizona, Arkansas, Delaware, District Of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, And West Virginia, Or "zone B." Additionally, If Not Included In "zone B" Above, Honda Is Recalling Certain 2008 Honda Accord, 2006-2008 Honda Civic, Civic Hybrid And Civic Ngv And 2007-2008 Honda Cr-v Vehicles Originally Sold, Or Ever Registered, In Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, And Wyoming. These Vehicles Are Equipped With Certain Air Bag Inflators Assembled As Part Of The Passenger Frontal Air Bag Modules Used As Original Equipment Or Replacement Equipment. In The Event Of A Crash Necessitating Deployment Of The Front Air Bags, These Inflators May Rupture Due To Propellant Degradation Occurring After Long-term Exposure To Absolute Humidity And Temperature Cycling.

Date	:	04-26-2017
Mileage	:	
Source	:	NICB
Details	:	Vehicle Status : Not Stolen

Date	:	04-26-2017
Mileage	:	
Source	:	Edmunds - True Market Value
Details	:	Trade-In : \$4,576 Private Sale : \$5,671 Dealers Retail : \$7,497

Odometer Records Source : NMVTIS

Odometer Information

No Odometer Information Found !!

Previous Vehicle Uses And Incidents

Your Vehicle Checks Out : VehicleHistory's database for this JHMFA36237S018913 shows No negative titles or other problems. When reported to VehicleHistory, these events can indicate serious past damage or other significant problems.



VEHICLE USE **NO ISSUES FOUND**

8 Vehicle Uses Checked:

0 Event(s) Reported

No Rental Use Record

No Issues Found

No Taxi Use Record

No Issues Found

No Police Use Record

No Issues Found

No Test Use Record

No Issues Found

No Accident/Salvage Record Reported Through Accident Data Source(s)

No Issues Found

No Rebuilt Title Record(s)

No Issues Found

No Undisclosed Lien Record(s)

No Issues Found

No Theft Record(s)

No Issues Found

Theft Records

No Theft or Theft Recovery Records Found !

Lien / Impound / Export Records

No Lien / Impound / Export Records Found!

Junk / Salvage / Insurance Record Source : NMVTIS

No Junk / Salvage / Insurance Record Found!

Salvage Auction Record



Exleasingcar Car Auctions

30+ manufacturers, 200+ models,
5500+ cars.

No Salvage Auction Record !

Sales Records

No sales records found!

Vehicle Recalls

Recalls:8

Service Bulletins: 8

Recall Subject: Service Brakes, Hydraulic:antilock:wheel Speed Sensor

Report Receipt Date: 09-05-2007

NHTSA Campaign: 07V399000

Manufacture: HONDA (AMERICAN HONDA MOTOR CO.)

Summary:

On Certain Vehicles, The Wheel Speed Sensor Housing Uses An O-ring Seal To Prevent Leakage To Or From The Wheel Bearing. If Assembled Improperly, The O-ring May Not Seal Properly Allowing Water To Enter The Wheel Bearing And Eventually Cause Damage To The Bearing, Especially In Areas Where Use Of Road Salt Is Prevalent. If The Driver Continues To Drive With This Condition It Is Possible For The Wheel Bearing To Become Loose, Which Could Cause The Bearing To Fail.

Consequence:

This Could Cause A Wheel To Fall Off Of The Vehicle, Possibly Resulting In A Crash.

Remedy:

Dealers Will Inspect The Rear Abs Sensors And Wheel Bearings For Damaged Parts And Replace Them Free Of Charge. The Recall Began On September 25, 2007. Owners May Contact Honda At 1-800-999-1009.

Recall Subject: Exterior Lighting:brake Lights:switch

Report Receipt Date: 09-05-2007

NHTSA Campaign: 07V402000

Manufacture: HONDA (AMERICAN HONDA MOTOR CO.)

Summary:

On Certain Sedan And Hybrid (cng) Vehicles, During Assembly, The Telescopic Steering Column Mechanism May Have Been Over-lubricated With Silicone Grease. Over Time, Some Of This Extra Grease May Drip On The Brake Light Switch Causing The Switch To Fail.

Consequence:

Failure May Result In A Loss Of Brake Lights And An Increased Risk That The Vehicle Could Be Struck In The Rear. In Addition, A Failed Brake Light Switch Could Prevent Shifting The Transmission From The Park Position (vehicles With An Automatic Transmission).

Remedy:

Dealers Will Replace The Brake Light Switch And Install A Protective Cover Overthe Switch Free Of Charge. The Recall Began On October 2, 2007. Owners May Contact Honda At 1-800-999-1009.

Recall Subject: Fuel System, Other:storage:tank Assembly

Report Receipt Date: 11-01-2007

NHTSA Campaign: 07V512000

Manufacture: HONDA (AMERICAN HONDA MOTOR CO.)

Summary:

On Certain Compressed Natural Gas (cng) Vehicles, In The Event Of A Severe Interior Fire In The Area Of The Rear Seat, The Cng Tank May Be Heated Unevenly, Preventing The Pressure Relief Device From Venting The Contents Of The Tank As Designed.

Consequence:

This Could Result In A Tank Rupture, Explosion, And Ejection Of The Tank From The Vehicle.

Remedy:

Dealers Will Install A Heat Insulator Material To The Rear Seat Back. An Interim Owner Letter Was Mailed To Owners Beginning November 26, 2007. When Parts Are Available, Owners Will Be Renotified Asking Them To Bring In Their Vehicle For Repair. Owners May Contact Honda At 1-800-999-1009.

Recall Subject: Electrical System

Report Receipt Date: 03-02-2011

NHTSA Campaign: 11V106000

Manufacture: HONDA (AMERICAN HONDA MOTOR CO.)

Summary:

Honda Is Recalling Certain Model Year 2006-2007 Honda Civic Hybrid Vehicles. There Is A Potential For The Voltage Converter That Relays Power From The Integrated Motor Assist (ima) System To The Vehicle's Electrical Components To Fail.

Consequence:

This Failure Will Cause The Headlights To Turn Off, The Engine To Stall, And Prevent The Vehicle From Being Restarted, Increasing The Risk Of A Crash.

Remedy:

Dealers Will Replace The Voltage Converter Free Of Charge. The Safety Recall Began On March 25, 2011. Owners May Contact Honda Customer Service At 1-800-999-1009 A Select Option 4.

Recall Subject: Air Bags:passenger Side Frontal

Report Receipt Date: 05-24-2016

NHTSA Campaign: 16V346000

Manufacture: Honda (American Honda Motor Co.)

Summary:

Honda (american Honda Motor Co.) Is Recalling Certain Model Year 2009-2011 Acura Tsx, 2011 Tsx Wagon, 2010-2011 Acura Zdx, 2008-2011 Honda Accord, 2010-2011 Accord Crosstour, 2006-2011 Civic, Civic Hybrid, And Civic Gx, 2007-2011 Cr-v, 2010-2011 Fcx Clarity And Insight, And 2009-2011 Fit, And Pilot Vehicles Originally Sold, Or Ever Registered, In Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, The Northern Mariana Islands (saipan), And The U.s. Virgin Islands, Or "zone A." Additionally, Unless Already Included In "zone A" Above, Honda Is Recalling Certain Model Year 2008 Honda Accord, 2006-2008 Civic, Civic Hybrid And Civic Gx, And 2007-2008 Cr-v Vehicles Originally Sold, Or Ever Registered, In Arizona, Arkansas, Delaware, The District Of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, And West Virginia, Or "zone B." Vehicles Not Originally Sold Or Ever Registered In Either Zones A Or B Are Not Subject To This Safety Recall. These Vehicles Are Equipped With Certain Air Bag Inflators Assembled As Part Of The Passenger Frontal Air Bag Modules, And Used As Original Equipment Or Replacement Equipment. In The Event Of A Crash Necessitating Deployment Of The Front Air Bags, These Inflators May Rupture Due To Propellant Degradation Occurring After Long-term Exposure To Absolute Humidity And Temperature Cycling.

Consequence:

An Inflator Rupture May Result In Metal Fragments Striking The Vehicle Occupants Resulting In Serious Injury Or Death.

Remedy:

Honda Will Notify Owners, And Dealers Will Replace The Inflator, Free Of Charge. The Recall Began March 2017. Owners May Contact Honda Customer Service At 1-888-234-2138. Honda's Numbers For This Recall Is Ka4, Ka5, Ka6, And Ka7.

Recall Subject: Air Bags:passenger Side Frontal

Report Receipt Date: 05-24-2016

NHTSA Campaign: 16V346000

Manufacture: Honda (American Honda Motor Co.)

Summary:

Honda (american Honda Motor Co.) Is Recalling Certain Model Year 2009-2011 Acura Tsx, 2011 Tsx Wagon, 2010-2011 Acura Zdx, 2008-2011 Honda Accord, 2010-2011 Accord Crosstour, 2006-2011 Civic, Civic Hybrid, And Civic Gx, 2007-2011 Cr-v, 2010-2011 Fcx Clarity And Insight, And 2009-2011 Fit, And Pilot Vehicles Originally Sold, Or Ever Registered, In Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, The Northern Mariana Islands (saipan), And The U.s. Virgin Islands, Or "zone A." Additionally, Unless Already Included In "zone A" Above, Honda Is Recalling Certain Model Year 2008 Honda Accord, 2006-2008 Civic, Civic Hybrid And Civic Gx, And 2007-2008 Cr-v Vehicles Originally Sold, Or Ever Registered, In Arizona, Arkansas, Delaware, The District Of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, And West Virginia, Or "zone B." Vehicles Not Originally Sold Or Ever Registered In Either Zones A Or B Are Not Subject To This Safety Recall. These Vehicles Are Equipped With Certain Air Bag Inflators Assembled As Part Of The Passenger Frontal Air Bag Modules, And Used As Original Equipment Or Replacement Equipment. In The Event Of A Crash Necessitating Deployment Of The Front Air Bags, These Inflators May Rupture Due To Propellant Degradation Occurring After Long-term Exposure To Absolute Humidity And Temperature Cycling.

Consequence:

An Inflator Rupture May Result In Metal Fragments Striking The Vehicle Occupants Resulting In Serious Injury Or Death.

Remedy:

Honda Will Notify Owners, And Dealers Will Replace The Inflator, Free Of Charge. The Recall Began March 2017. Owners May Contact Honda Customer Service At 1-888-234-2138. Honda's Numbers For This Recall Is Ka4, Ka5, Ka6, And Ka7.

Recall Subject: Air Bags:passenger Side Frontal

Report Receipt Date: 01-10-2017

NHTSA Campaign: 17V030000

Manufacture: Honda (American Honda Motor Co.)

Summary:

Honda (american Honda Motor Co.) Is Recalling Certain 2009-2012 Acura Tsx, 2011-2012 Acura Tsx Wagon, 2010-2012 Acura Zdx, 2008-2012 Honda Accord, 2010-2012 Honda Accord Crosstour And Honda Insight, 2009-2012 Honda Fit, 2009-2012 Pilot, 2007-2011 Honda Cr-v, 2012 Honda Fcx Clarity And 2006-2011 Honda Civic, Civic Hybrid, Civic Ngv Vehicles Originally Sold, Or Ever Registered, In Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, The Northern Mariana Islands (saipan), And The U.s. Virgin Islands, Or "zone A." Additionally, If Not Included In "zone A" Above, Honda Is Recalling Certain 2009 Acura Tsx, Honda Fit And Pilot, 2008-2009 Honda Accord, 2006-2009 Civic, Civic Hybrid And Civic Ngv, And 2007-2009 Honda Cr-v Vehicles Originally Sold, Or Ever Registered, In Arizona, Arkansas, Delaware, District Of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, And West Virginia, Or "zone B." Additionally, If Not Included In "zone B" Above, Honda Is Recalling Certain 2008 Honda Accord, 2006-2008 Honda Civic, Civic Hybrid And Civic Ngv And 2007-2008 Honda Cr-v Vehicles Originally Sold, Or Ever Registered, In Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, And Wyoming.

4/26/2017Free Vehicle History Report - Vehicle Specifications

These Vehicles Are Equipped With Certain Air Bag Inflators Assembled As Part Of The Passenger Frontal Air Bag Modules Used As Original Equipment Or Replacement Equipment. In The Event Of A Crash Necessitating Deployment Of The Front Air Bags, These Inflators May Rupture Due To Propellant Degradation Occurring After Long-term Exposure To Absolute Humidity And Temperature Cycling.

Consequence:

An Inflator Rupture May Result In Metal Fragments Striking The Vehicle Occupants Resulting In Serious Injury Or Death.

Remedy:

Honda Will Notify Owners, And Dealers Will Replace The Front Passenger Side Air Bag Inflator, Free Of Charge. The Manufacturer Has Mailed An Interim Notification, And Will Send A Second Notification When Parts Are Available. Owners May Contact Honda Customer Service At 1-888-234-2138. Honda's Numbers For This Recall Are Ke1 And Ke2.

Recall Subject: Air Bags:passenger Side Frontal

Report Receipt Date: 01-10-2017

NHTSA Campaign: 17V030000

Manufacture: Honda (American Honda Motor Co.)

Summary:

Honda (american Honda Motor Co.) Is Recalling Certain 2009-2012 Acura Tsx, 2011-2012 Acura Tsx Wagon, 2010-2012 Acura Zdx, 2008-2012 Honda Accord, 2010-2012 Honda Accord Crosstour And Honda Insight, 2009-2012 Honda Fit, 2009-2012 Pilot, 2007-2011 Honda Cr-v, 2012 Honda Fcx Clarity And 2006-2011 Honda Civic, Civic Hybrid, Civic Ngv Vehicles Originally Sold, Or Ever Registered, In Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, The Northern Mariana Islands (saipan), And The U.s. Virgin Islands, Or "zone A." Additionally, If Not Included In "zone A" Above, Honda Is Recalling Certain 2009 Acura Tsx, Honda Fit And Pilot, 2008-2009 Honda Accord, 2006-2009 Civic, Civic Hybrid And Civic Ngv, And 2007-2009 Honda Cr-v Vehicles Originally Sold, Or Ever Registered, In Arizona, Arkansas, Delaware, District Of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, And West Virginia, Or "zone B." Additionally, If Not Included In "zone B" Above, Honda Is Recalling Certain 2008 Honda Accord, 2006-2008 Honda Civic, Civic Hybrid And Civic Ngv And 2007-2008 Honda Cr-v Vehicles Originally Sold, Or Ever Registered, In Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, And Wyoming. These Vehicles Are Equipped With Certain Air Bag Inflators Assembled As Part Of The Passenger Frontal Air Bag Modules Used As Original Equipment Or Replacement Equipment. In The Event Of A Crash Necessitating Deployment Of The Front Air Bags, These Inflators May Rupture Due To Propellant Degradation Occurring After Long-term Exposure To Absolute Humidity And Temperature Cycling.

Consequence:

An Inflator Rupture May Result In Metal Fragments Striking The Vehicle Occupants Resulting In Serious Injury Or Death.

Remedy:

Honda Will Notify Owners, And Dealers Will Replace The Front Passenger Side Air Bag Inflator, Free Of Charge. The Manufacturer Has Mailed An Interim Notification, And Will Send A Second Notification When Parts Are Available. Owners May Contact Honda Customer Service At 1-888-234-2138. Honda's Numbers For This Recall Are Ke1 And Ke2.

The above recalls were issued for the 2007 Honda Civic by NHTSA.

Please call the National Highway Traffic and Safety Administration Auto Safety Hotline at 1-888-DASH-2-DOT (1-888-327-4236) to report safety defects or to obtain information on cars, trucks, child seats, and highway or traffic safety. We do not review, validate, or edit the data provided by the NHTSA.

Technical Service Bulletins (TSBs)

Free DataSheet PDF Search Site - No Registering Required.

Download PDF Datasheets for Free. Go to [datasheetspdf.com](#)

Your Vehicle Checks Out: These "secret warranties," TSBs cover known problems and provide repair instructions for service technicians and accordingly are distributed to all of the manufacturer's dealerships. Generally these repairs will be free of charge only if the vehicle is still under warranty.

73 SERVICE RECORD FOUND

DATE	COMPONENT	DETAILS
11-16-2006	061000 Engine And Engine Cooling:engine	Damaged Terminal Or Poor Connection At Terminal F5 Yel At The Underdash Fuse Box F Connector Can Cause Indication Of Dtc S To Repair These Dtc S Properly Engage Or Replace The Damaged Terminal *kb
07-18-2007	021000 Suspension:front	Popping Noise In The Front Suspension While Turning *kb
11-16-2007	040000 Service Brakes, Air	Brake Pedal Can Feel Hard During The First Couple Of Brake Applications Usually In The Morning When The Ambient Temperature Is Cold *nj
11-22-2007	136000 Visibility:windshield Wiper/washer	Windshield Wipers Intermittently Do Not Park Or Turn Off *nj Updated 2 21 08 *nj
12-01-2007	061110 Engine And Engine Cooling:engine:gasoline:belts And Associated Pulleys	Install Crankshaft Pulley Correctly To Prevent Oil Pump Damage *nj
02-08-2008	022000 Suspension:rear	Uneven Or Rapid Rear Tire Wear *nj
03-01-2008	114000 Electrical System:wiring	Mil On With Dtc P0111 P0128 P2183 Or P2185 Check Ect Sensor 2 *nj

DATE	COMPONENT	DETAILS
03-14-2008	091130 Fuel System, Other:storage:tank Assembly:pressure Relief Devices	Mil Comes On With Dtc P0456 Evap System Very Small Leak Detected *nj
05-09-2008	117000 Digital Instrument Panel	Honda Warranty Extension-vehicle Warranty Mileage Class Action Lawsuit Alleging That The Odometers On Certain 2002-2006 Honda Models Were Overstating Mileage Federal Court Provided Final Approval Of Settlement On 12 29 07 No Models
05-31-2008	355100 Equipment:other:labels	Load Carrying Capacity Reduced Label For All Honda Vehicles *pe
07-18-2008	102000 Power Train>manual Transmission	Honda Transmission Grinds When Shifting Into 3rd Gear Pops Out Of 3rd Gear Or Is Hard To Shift Into 3rd Gear *pe Updated 4 8 11 *pe
08-01-2008	141000 Air Bags:frontal	Honda Srs Indicator On With Srs Dtc 81-63 85-63 Or 81-79 Just Replaced The Srs Unit And Now The Srs Indicator I S On With One Or More Of These Srs Dtc The Wrong Part May Have Been Installed Even Though Box Indicate Correct One
08-06-2008	111000 Electrical System:battery	Honda Hybrid Batteries Can Be Affected And Damaged By Excessively High Temperatures *pe
08-15-2008	061110 Engine And Engine Cooling:engine:gasoline:belts And Associated Pulleys	Honda Due To A Manufacturing Problem The Water Pump Pulley Bolts May Lose Tension And Eventually Come Loose Loose Pulley Bolts May Produce A Pulley Noise And Could Cause The Drive Belt To Break Csc Letter Was Received *pe
08-22-2008	030000 Service Brakes, Hydraulic	Honda The Advanced Hydraulic Booster Ahb Brake System Makes A Pronounced Short Buzzy Grunt When The Brake Pedal Is Pressed *pe
08-22-2008	035000 Service Brakes, Hydraulic:fluid	Honda The Advanced Hydraulic Booster Ahb Brake System Makes A Pronounced Short Buzzy Grunt When The Brake Pedal Is Pressed *pe
09-17-2008	136000 Visibility:windshield Wiper/washer	Honda When The Windshield Wipers Are Turned Off They Intermittently Do Not Stop Park At The Correct Location At The Bottom Of The Windshield Or They Continue To Run *pe
09-17-2008	136200 Visibility:windshield Wiper/washer:motor	Honda When The Windshield Wipers Are Turned Off They Intermittently Do Not Stop Park At The Correct Location At The Bottom Of The Windshield Or They Continue To Run *pe
07-30-2009	060000 Engine And Engine Cooling	Honda See Document Search Button For Owner Letter Engine Overheats Or Leaks Coolant The Engine Block Is Cracking At The Coolant Passages Install A New Engine Block Assembly *pe
07-30-2009	061000 Engine And Engine Cooling:engine	Honda See Document Search Button For Owner Letter Engine Overheats Or Leaks Coolant The Engine Block Is Cracking At The Coolant Passages Install A New Engine Block Assembly *pe
08-13-2010	141000 Air Bags:frontal	Honda The Srs Indicator Is On And Dtc 32-10 Open In The Front Passenger S Side Airbag Inflator Is Stored This Problem May Be Intermittent Under The Front Passenger S Seat The Srs Portion Of The Floor Wire Harness Has A Poor Crimp In
11-24-2010	061000 Engine And Engine Cooling:engine	Honda Vehicle Engine Oil Leak At The Cylinder Head Cover There Is Paint Overspray In The Gasket Groove Of The Cylinder Head Cover *pe
12-01-2010	111000 Electrical System:battery	Honda Service Campaign See Document Search Button For Owner Letter The Battery May Pre-maturely Fail And It Is A Software Problem *rm
12-01-2010	118000 Electrical System: Software	Honda Service Campaign See Document Search Button For Owner Letter The Battery May Pre-maturely Fail And It Is A Software Problem *rm
03-01-2011	138110 Visibility:defroster/defogger System:windshield:blower	Honda Engineering Request For Investigation Inspecting Certain Model Vehicles 4 Door Vin Staring With 1hg That Are With In Warranty And Have A Complaint That The Blower Motor Is Inoperative Slow Or Intermittent *pe
05-13-2011	103100 Power Train:automatic Transmission:control Module (tcm, Pcm)	Honda Repeatedly Shifting Between R And D At High Wheel Speed When Stuck In Snow Can Cause Transmission Damage *rm

DATE	COMPONENT	DETAILS
07-12-2011	101100 Power Train:clutch Assembly:pedal/linkage	Honda The Clutch Pedal Pops Or Squeaks When It Is Pressed There Is Insufficient Clearance Of The Master Cylinder *rm Updated 7 29 11 *pe
07-15-2011	103100 Power Train:automatic Transmission:control Module (tcm, Pcm)	Harsh Transmission Engagement After Auto Idle Stop Hybrid Only *nj Updated 7 29 11 *pe
07-19-2011	062000 Engine And Engine Cooling:cooling System	Honda Malfunction Light Is On With Trouble Codes Stored Due To A Software Problem 2006-2008 Civic Hybrid *rm
07-21-2011	061000 Engine And Engine Cooling:engine	Honda The Malfunction Light Is On With A Trouble Code Stored Due To A Software Problem *rm
07-21-2011	091130 Fuel System, Other:storage:tank Assembly:pressure Relief Devices	Honda The Malfunction Light Is On With A Trouble Code Stored Due To A Software Problem *rm
07-21-2011	103000 Power Train:automatic Transmission	Honda The Malfunction Light Is On With A Trouble Code Stored Due To A Software Problem *rm
08-10-2011	071200 Fuel System, Gasoline:storage:auxillary Tank	Honda Fuel Tank Assembly Warranty Information *rm
01-12-2012	112000 Electrical System:alternator/generator/regulator	Honda On Some Model Vehicles There Is An Alternator Starter Tester Ast Module Capable Of Testing Alternators Installed On Gr8 Diagnostic Battery Station *pe
01-12-2012	113000 Electrical System:starter Assembly	Honda On Some Model Vehicles There Is An Alternator Starter Tester Ast Module Capable Of Testing Alternators Installed On Gr8 Diagnostic Battery Station *pe
03-02-2012	021000 Suspension:front	Honda When Make Tight Turn Would Hear Or Feel A Popping Or Clunking Noise After Driving Over Bumps Coming From The Front Suspension *pe
04-24-2012	111000 Electrical System:battery	Honda Hybrid Vehicle Battery Exchange Information *rm Updated 5 2 12 *js
08-24-2012	350000 Equipment	Honda See Document Search Button For Owner Letter On Some Vehicles The Blue Paint Or Black Paint Leading Edge Of Front Fenders And On Hood May Crack And An Extended Warranty Has Been Issued Models 2006-12 Civic *pe
12-21-2012	111000 Electrical System:battery	Honda Warranty Coverage Has Been Extended On Some Vehicles For The Ima Battery Module Models 2003-2008 Civic Hybrids *pe
03-29-2013	071100 Fuel System, Gasoline:storage:tank Assembly	Honda The Fuel Tank And Solenoid Valve Are No Longer Being Replaced Together And If Fuel Tank Solenoid Valve Is Replaced Then Reinstall Original Fuel Tank Models 1998-11 Civic Gx 2012-13 Civic *pe Updated 04 15 2013 *kb
05-01-2013	190000 Tires	Honda The Engine Shuts Off Power On But In Accessory Never Use Conventional Wheel Tire Assemblies On Pax Vehicles Mil On After Throttle Body Cleaning Or Replacement S M Fix Brake System Bleeding Dialogue For Dvd Surround Sound Fr
05-01-2013	200000 Wheels	Honda The Engine Shuts Off Power On But In Accessory Never Use Conventional Wheel Tire Assemblies On Pax Vehicles Mil On After Throttle Body Cleaning Or Replacement S M Fix Brake System Bleeding Dialogue For Dvd Surround Sound Fr
05-01-2013	353400 Equipment:electrical:radio/tape Deck/cd Etc.	Honda The Engine Shuts Off Power On But In Accessory Never Use Conventional Wheel Tire Assemblies On Pax Vehicles Mil On After Throttle Body Cleaning Or Replacement S M Fix Brake System Bleeding Dialogue For Dvd Surround Sound Fr
05-01-2013	030000 Brakes (pws)	Honda The Engine Shuts Off Power On But In Accessory Never Use Conventional Wheel Tire Assemblies On Pax Vehicles Mil On After Throttle Body Cleaning Or Replacement S M Fix Brake System Bleeding Dialogue For Dvd Surround Sound Fr
05-01-2013	060000 Engine (pws)	Honda The Engine Shuts Off Power On But In Accessory Never Use Conventional Wheel Tire Assemblies On Pax Vehicles Mil On After Throttle Body Cleaning Or Replacement S M Fix Brake System Bleeding Dialogue For Dvd Surround Sound Fr

DATE	COMPONENT	DETAILS
06-05-2013	105300 Power Train:driveline:driveshaft	Honda A Clicking Or Clacking Noise Is Heard When Turning Either Left Or Right In Some Vehicles Models 2006-2012 Civic *pe
06-19-2013	111000 Electrical System:battery	Honda Information On Replacement And Removal Of Junction Board From Old Ima Battery And New Battery Mounted Before Battery Is Installed Models 2003-11 Civic Hybrid 2011-12 Cr-z 2000-06 Insight 2010-12 Insight *pe Updated
07-31-2013	105300 Power Train:driveline:driveshaft	Honda Due To A Clicking Or Clacking Noise While Turning Either Left Or Right The Cause Of The Noise Is Under Investigation Model 2006-2012 Civic *pe
09-09-2013	190000 Tires	Dealer Message - On June 14 2013 In Connection With The Settlement Of A Class Action Lawsuit American Honda Announced A Limited Warranty Extension For Some 2006-07 Civic And 2006-08 Civic Hybrid Vehicles The Warranty Extension Covers T
09-13-2013	162900 Structure:body:roof And Pillars	Dealer Message - On August 13 2013 American Honda Announced Two Warranty Extensions For Some 2006-2011 Civic Vehicles The Warranty Extensions Cover The Refinishing Of Hood Roof And Trunk As Needed
09-13-2013	162000 Structure:body	Dealer Message - On August 13 2013 American Honda Announced Two Warranty Extensions For Some 2006-2011 Civic Vehicles The Warranty Extensions Cover The Refinishing Of Hood Roof And Trunk As Needed
01-18-2014	111000 Electrical System:battery	Honda There Are New Battery Software And Hardware Updates *rm Updated 3 06 12 *pe Updated 02 26 2014 *js
01-18-2014	118000 Electrical System: Software	Honda There Are New Battery Software And Hardware Updates *rm Updated 3 06 12 *pe Updated 02 26 2014 *js
02-26-2014	190000 Tires	Honda On Some Vehicles Tires In An Advanced Stage Of Diagonal Or Inner Edge Wear May Vibrate At Highway Speeds And Or Make Roaring Noise Due To Rear Suspension Geometry Camber On Some Models Causing Rapid And Or Uneven Tire Wear Mo
09-01-2014	060000 Engine And Engine Cooling	Honda Civic See Document Search Button For Owner Letter The Engine Cylinder Block Is Experiencing Over Heating On 2006-09 Civics *lj
09-16-2014	010000 Steering	Honda The Steering Feels Heavy And There Is A Stored Trouble Code There Is A Malfunction Of The Power Steering *rm Update 03 03 15*lj
09-23-2014	016000 Steering:electric Power Assist System	Honda See Document Search Button For Owner Letter Warranty Extension Due To Electric Power Steering With Code Dtc 32-09 Or 61-04 Model 2007-08 Fit *lj
10-01-2014	016000 Steering:electric Power Assist System	Honda When Vehicle Is Not Moving Electric Power Steering Feels Heavier And Hard To Turn And An Extended Warranty Has Been Issued For Some To 10 Years From Original Date Of Purchase Or 150 000 Model 2006-09 Civic Si
10-01-2014	016000 Steering:electric Power Assist System	Honda See Document Search Button For Owner Letter An Extended Warranty Has Been Issue To Some Vehicles Due To Electric Power Steering Being Heavier Than Normal And Also Very Hard To Turn When Vehicle Is Not Moving Model 2006-07 Civic
12-21-2014	100000 Power Train	American Honda Has Extended Warranty For All 2006-2007 Civic Hybrid Due To Power Steering Control Unit *lj
03-31-2015	091200 Fuel System, Other:storage:fuel Gauge System	Fuel Gauge Out Of Order Low Fuel Indicator Flashes While The Tank Has Fuel*cn
08-21-2016	355200 Equipment:other:owners/service/other Manual	Advertisement In Hawaiian Newspapers To Remind Owners Of The Takata Recall And To Schedule An Appointment At Their Earliest Convenience
08-23-2016	355200 Equipment:other:owners/service/other Manual	Us Virgin Islands Newspaper Advertisements To Remind Owners Of The Takata Recall And To Schedule An Appointment At Their Earliest Convenience
08-23-2016	355200 Equipment:other:owners/service/other Manual	Text Messages Sent To Remind Owners Of The Takata Recall And To Schedule An Appointment At Their Earliest Convenience

DATE	COMPONENT	DETAILS
08-26-2016	200000 Wheels	Service Bulletin - During Assembly Some Wheel Speed Sensors May Have Been Improperly Installed And Do Not Seal The Hub Assembly Water May Enter The Hub Assembly And Damage The Wheel Bearing In Areas Where Road Salt Is Used The Wheel Bear
08-26-2016	046300 Service Brakes, Air:antilock:wheel Speed Sensor	Service Bulletin - During Assembly Some Wheel Speed Sensors May Have Been Improperly Installed And Do Not Seal The Hub Assembly Water May Enter The Hub Assembly And Damage The Wheel Bearing In Areas Where Road Salt Is Used The Wheel Bear
08-29-2016	355200 Equipment:other:owners/service/other Manual	Letter Sent In Conjunction With The Florida Highway Safety And Motor Vehicles Department To Remind Florida Owners Of The Takata Recall And To Schedule An Appointment At Their Earliest Convenience
09-07-2016	355200 Equipment:other:owners/service/other Manual	Flyer Circulated To The Residents Of Hawaii To Remind Owners Of The Takata Recall And To Schedule An Appointment At Their Earliest Convenience
09-07-2016	355200 Equipment:other:owners/service/other Manual	Posters Sent To Hawaiian Independent Repair Facilities Automotive Part Stores Car Washes And Gas Stations To Remind Owners Of The Takata Recall And To Schedule An Appointment At Their Earliest Convenience
09-30-2016	140000 Air Bags	Tech2tech Video - Airbag Inflator Installation Tips Please Advise If You Would Like A Copy Of The Video Sent To You On A Thumb Drive Or Dvd
10-01-2016	140000 Air Bags	Tech2tech Video - Airbag Inflator Installation Tips Please Advise If You Would Like A Copy Of The Video Sent To You On A Thumb Drive Or Dvd
10-04-2016	091100 Fuel System, Other:storage:tank Assembly	Service Bulletin - The Fuel Gauge Does Not Work And The Low Fuel Indicator Blinks With Fuel In The Tank The Pcm May Need To Be Replaced
10-04-2016	091200 Fuel System, Other:storage:fuel Gauge System	Service Bulletin - The Fuel Gauge Does Not Work And The Low Fuel Indicator Blinks With Fuel In The Tank The Pcm May Need To Be Replaced

Accident Records

Your Vehicle Checks Out: There have been No accidents reported to VehicleHistory.com for this vehicle. The accident records on vehicle history are composed of a number of state sources and some independent agencies, they are based strictly on the information that is available to us.

No ACCIDENT **FOUND ON RECORD**

No Accident Records!

62 Title/Problems Area's Checked Source : NMVTIS

Your Vehicle Has No Incident : There have been No title problems reported to VehicleHistory.com for this vehicle. VehicleHistory.com receives its title information from government sources and independent agencies, and based on the information available to us.

No TITLE ISSUE(S) **FOUND ON RECORD**

Free DataSheet PDF Search Site - No Registering Required.

Download PDF Datasheets for Free. Go to datasheetspdf.com

Flood damage

No Issues Found Not Reported As A Flood damage To VehicleHistory

Fire damage

No Issues Found Not Reported As A Fire damage To VehicleHistory

Hail damage

No Issues Found Not Reported As A Hail damage To VehicleHistory

Salt water damage

No Issues Found Not Reported As A Salt water damage To VehicleHistory

Vandalism

No Issues Found Not Reported As A Vandalism To VehicleHistory

Kit

No Issues Found Not Reported As A Kit To VehicleHistory

Dismantled

No Issues Found Not Reported As A Dismantled To VehicleHistory

Junk

No Issues Found Not Reported As A Junk To VehicleHistory

Rebuilt

No Issues Found Not Reported As A Rebuilt To VehicleHistory

Reconstructed

No Issues Found Not Reported As A Reconstructed To VehicleHistory

Salvage: Damage or Not Specified

No Issues Found Not Reported As A Salvage: Damage or Not Specified To VehicleHistory

Test Vehicle

No Issues Found Not Reported As A Test Vehicle To VehicleHistory

Refurbished

No Issues Found Not Reported As A Refurbished To VehicleHistory

Collision

No Issues Found Not Reported As A Collision To VehicleHistory

Salvage Retention

No Issues Found Not Reported As A Salvage Retention To VehicleHistory

Prior Taxi

No Issues Found Not Reported As A Prior Taxi To VehicleHistory

Prior Police

No Issues Found Not Reported As A Prior Police To VehicleHistory

Original Taxi

No Issues Found Not Reported As A Original Taxi To VehicleHistory

Original Police

No Issues Found Not Reported As A Original Police To VehicleHistory

Remanufactured

No Issues Found Not Reported As A Remanufactured To VehicleHistory

Gray Market

No Issues Found Not Reported As A Gray Market To VehicleHistory

Warranty Return

No Issues Found Not Reported As A Warranty Return To VehicleHistory

Antique

No Issues Found Not Reported As A Antique To VehicleHistory

Classic

No Issues Found Not Reported As A Classic To VehicleHistory

Agricultural Vehicle

No Issues Found Not Reported As A Agricultural Vehicle To VehicleHistory

Logging Vehicle

No Issues Found Not Reported As A Logging Vehicle To VehicleHistory

Street Rod

No Issues Found Not Reported As A Street Rod To VehicleHistory

Vehicle Contains Reissued VIN

No Issues Found Not Reported As A Vehicle Contains Reissued VIN To VehicleHistory

Replica

No Issues Found Not Reported As A Replica To VehicleHistory

Totaled

No Issues Found Not Reported As A Totaled To VehicleHistory

Owner Retained

No Issues Found Not Reported As A Owner Retained To VehicleHistory

Bond Posted

No Issues Found Not Reported As A Bond Posted To VehicleHistory

Memorandum Copy

No Issues Found Not Reported As A Memorandum Copy To VehicleHistory

Parts Only

No Issues Found Not Reported As A Parts Only To VehicleHistory

Recovered Theft

No Issues Found Not Reported As A Recovered Theft To VehicleHistory

Undisclosed Lien

No Issues Found Not Reported As A Undisclosed Lien To VehicleHistory

Prior Owner Retained

No Issues Found Not Reported As A Prior Owner Retained To VehicleHistory

Vehicle Non-conformity Uncorrected

No Issues Found Not Reported As A Vehicle Non-conformity Uncorrected To VehicleHistory

Vehicle Non-conformity Corrected

No Issues Found Not Reported As A Vehicle Non-conformity Corrected To VehicleHistory

Vehicle Safety Defect Uncorrected

No Issues Found Not Reported As A Vehicle Safety Defect Uncorrected To VehicleHistory

Vehicle Safety Defect Corrected

No Issues Found Not Reported As A Vehicle Safety Defect Corrected To VehicleHistory

VIN Replaced

No Issues Found Not Reported As A VIN Replaced To VehicleHistory

Gray Market: Non-compliant

No Issues Found Not Reported As A Gray Market: Non-compliant To VehicleHistory

Gray Market: Compliant

No Issues Found Not Reported As A Gray Market: Compliant To VehicleHistory

Manufacturer Buy Back

No Issues Found Not Reported As A Manufacturer Buy Back To VehicleHistory

Former Rental

No Issues Found Not Reported As A Former Rental To VehicleHistory

Salvage: Stolen

No Issues Found Not Reported As A Salvage: Stolen To VehicleHistory

Salvage: Reasons Other Than Damage or Stolen

No Issues Found Not Reported As A Salvage: Reasons Other Than Damage or Stolen To VehicleHistory

Disclosed Damage

No Issues Found Not Reported As A Disclosed Damage To VehicleHistory

Prior Non-Repairable / Repaired

No Issues Found Not Reported As A Prior Non-Repairable / Repaired To VehicleHistory

Crushed

No Issues Found Not Reported As A Crushed To VehicleHistory

Odometer: Actual

No Issues Found Not Reported As A Odometer: Actual To VehicleHistory

No Issues Found	Not Reported As A Odometer: Actual To VehicleHistory
Odometer: Not Actual	
No Issues Found	Not Reported As A Odometer: Not Actual To VehicleHistory
Odometer: Tampering Verified	
No Issues Found	Not Reported As A Odometer: Tampering Verified To VehicleHistory
Odometer: Exempt from Odometer Disclosure	
No Issues Found	Not Reported As A Odometer: Exempt from Odometer Disclosure To VehicleHistory
Odometer: Exceeds Mechanical Limits	
No Issues Found	Not Reported As A Odometer: Exceeds Mechanical Limits To VehicleHistory
Odometer: May be Altered	
No Issues Found	Not Reported As A Odometer: May be Altered To VehicleHistory
Odometer: Replaced	
No Issues Found	Not Reported As A Odometer: Replaced To VehicleHistory
Odometer: Reading at Time of Renewal	
No Issues Found	Not Reported As A Odometer: Reading at Time of Renewal To VehicleHistory
Odometer: Discrepancy	
No Issues Found	Not Reported As A Odometer: Discrepancy To VehicleHistory
Odometer: Call Title Division	
No Issues Found	Not Reported As A Odometer: Call Title Division To VehicleHistory
Odometer: Exceeds Mechanical Limits Rectified	
No Issues Found	Not Reported As A Odometer: Exceeds Mechanical Limits Rectified To VehicleHistory

VehicleHistory.com - Overall Summary

Accident / Junk / Salvage / Insurance Records	
0 Records Found	Click Here To View (new-report.php#junk_salvage)
Theft Data	
0 Records Found	Click Here To View (new-report.php#theft)
Vehicle Specifications	
8 Records Found	Click Here To View (specifications.php)
Equipment Details	
20 Records Found	Click Here To View (equipment-details.php)
True Market Value	
1 Records Found	Click Here To View (true-market-value.php)
Vehicle Performance	
3 Records Found	Click Here To View (vehicle-performance.php)
Fuel Efficiency	
3 Records Found	Click Here To View (fuel-efficiency.php)
Safety Rating	
1 Records Found	Click Here To View (safety-rating.php)
Inspection checklist	
11 Records Found	Click Here To View (inspection-checklist.php)
Recalls & Defects	
8 Records Found	Click Here To View (recalls-and-defects.php)
Current Warranty	
6 Records Found	Click Here To View (current-warranty.php)
NHTSA Service Bulletins	
73 Records Found	Click Here To View (nhtsa-service-bulletins.php)
Summary Review	
2 Records Found	Click Here To View (summary-review.php)
Owner Reviews	
50 Records Found	Click Here To View (owner-reviews.php)
f Share on	
Facebook (https://www.facebook.com/dialog/feed?app_id=184683071273&link=https://www.vehiclehistory.com/vehicle?ZkVScWdBVnk40UXcwYk54cmRwNG9BMVIUYTQ4UFhZK0x4VDJtZWtxVUptWT0=&1493205984&picture=https://d3rdv3saj7j6nd.cloudfront.net/images/vehicle/sm/2007/2007-honda/2007-honda-civic-lx-coupe-at/2007-honda-civic-lx-coupe-at-grille.jpg&name=&caption=%20&description=&redirect_uri=http%3A%2F%2Fwww.facebook.com%2F)	
t Share on	
Twitter (https://twitter.com/home?status=Vehicle%20History%20For%20VIN%20JHMF36237S018913%202007%20Honda%20Civic%20https://www.vehiclehistory.com/vehicle?ZkVScWdBVnk40UXcwYk54cmRwNG9BMVIUYTQ4UFhZK0x4VDJtZWtxVUptWT0=&1493205984)	
Continue To Next Report Page ▶ (/paging-vin-report-data/specifications.php)	

VehicleHistory.com - Data Sources

- NMVTIS (Federal Government Salvage Database)
 - Junk Yards
 - Insurance Companies
 - Salvage Yards
 - Manufacturers
 - Car Dealerships
 - Auto Recyclers
 - Auto Auctions
 - Law Enforcement Agencies
 - Collision Repair Facilities
- *All states are required by law to report this information